

CASE STUDY

Delay Is Not an Option

Cooperative Effort Keeps Client Moving Forward

The Challenge:

A client had many wells in the DJ Basin requiring prep for fracturing operations on short notice. Most of the wells required darts to be placed in the liner top for pressure testing of the intermediate casing. The client called on Allied-Horizontal to work with a competitor that lacked the large 10K ID lubricator needed for this specialized work.

Our Response:

Understanding that delay was not an option for this client, Allied-Horizontal worked with the competing wireline provider to ensure the dart placement and testing was timely, providing the necessary 10K ID lubricator equipment and personnel needed for the specialized operation.



The Result:

Because of the cooperative effort of Allied-Horizontal working with the competitor wireline company, all wells completed on time and the client was very pleased at how Allied-Horizontal resolved this dilemma.

